

CREW: 62 WORK ORDER TYPE: PM REPAIR

02-53663-80

ISSUE DATE 01/06/11

Page 1 Of 1

Originator	: KEVIN MILLER	Schedule Date	:
Planner	: KEVIN MILLER	Priority	: 3C
Drawing No	: 1CCE-M2014	Clearance	: NO
Equip No/Cat	: 1CCE--A 1	Tag Request	:
Project ID	:	Text ID	:
Shutdown	: N No Shutdown	Frequency	: NOT SCHEDULED
Ref No	:	Last Reading	: No Reading

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : Signature :

\*\* Delay Codes Legend \*\*

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan

**\*\* Record Time Daily \*\***

## Delays

Step	Job Scope	MN	DY	Safety and Additional Information
------	-----------	----	----	-----------------------------------

Emp No	Date	Hours	Code/Hrs
--------	------	-------	----------

1 CLEAN UP ALL REMOVED ID FAN DRIVES AND  
PLACE IN SCRAP METAL DUMPSTERS PROVIDED.

\*\*\*\*\*

JOB SCOPE:

1. VANCE'S CREW WAS RESPONSIBLE FOR THE  
INSTALLATION OF THE NEW DRIVES THIS PAST  
OUTAGE. IT IS TIME NOW TO CLEAN UP THE  
AREA EAST OF THE SCRUBBER.

2. MARK CHASE AND GARY GOOLD ARE GOING TO HAVE THE FIRST DUMPSTER PLACED BY THE SCRUBBER. LOAD ALL METAL ITEMS INTO THE SCRAP METAL DUMPSTER. FOR ANY REMAINING ITEMS OBTAIN SUPV DIRECTION FOR THE DISPOSITION OF THIS MATERIAL. NONE OF IT IS GOING INTO THE WAREHOUSE.

\*\* IMPORTANT NOTICE \*\*

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



**IP7013395**